

## PREVENTATIVE MAINTENANCE

## MILLS 24-POINT INSPECTION

	CE DATE: / / SUPPORT TICKET #:
C	OMPANY: CUSTOMER #:
	SERIAL #: MODEL:
mplete fo	orm by placing a checkmark in the boxes as task are completed.
1 🗌	Update software when applicable. Verify error logging is turned on (code 319) for SMX, KMX and RMX.
2	Tram the head. Record values: Side to side Front to back
3	a) Check TRAK Sensors and M5 Bases. Replace wiper pads and chip scrapers. Check mounting of brackets. b) Check Glass Scales and Reader Head mounting.
4	Lubricate head, add oil and grease. Fill lube pump and inspect lubrication system.
5	Check alignment of Z-axis (only 3-axis knee mill or retrofit)
6	Run spindle through the Low, Neutral, and High gear ranges. Note any issues below. (Excludes retrofit) Check functionality of spindle fan and brake resistor fans (RMX).
7	If programmable spindle control, inspect and adjust spindle belt.
8	Check spindle brakes. Spindle stop? Yes No
9	Check and adjust level of machine, unless retrofit.
10	Adjust all gibs (including knee)
11	Adjust and inspect axis servo motor belts and drive train assemblies. Use belt tension tool on RMX.
12	Run Service Codes 11, 12, 128, 100, 101, 102, 103. Make adjustments as needed.
13	Calibrate X, Y and Z (quill) axis. Calibrate ram and check backlash.
14	Record positioning accuracy: X: Y: Z:
15	Record uni-directional repeatability: X: Y: Z:
16	Record bi-directional repeatability:  X:  Y:  Z:
17	Check all cables and cable connections. All cables should be neat and securely tied. Inspect cables inside electrical cabinet, tighten if needed for RMX.
18	Check if emergency stop button disables the control.
19	Check functionality of auxiliary functions when applicable.
20	Inspect X, Y, and Z limit switches. Set to full travel.
21	Jog the X, Y and Z-axis and listen for any unusual noises.
22	Inspect Electronic Handwheels. Clean friction pucks as needed.
23	Replace pendant fan filter (N/A on RMX).
	Wipe machine down. Clean touchscreen on RMX.

F10232-2 REV041719