

## **VMC2 Release notes**

### Version 2.0.4

- Fixed Bug 12412 - MTConnect Giving Incorrect Part Count when running GCD programs

### Version 2.0.3

- Fixed Bug 12277 - Z remained at cutting depth when system displayed RUN OVER
- Fixed Bug 12282 -- RUN does not take the Z up to Retract or activate coolant if atc tool is already loaded in spindle.

### Version 2.0.2

- Original Release.