



Southwestern Industries, Inc

White Paper

December 1, 2006

Modification of Power Draw Bars

The design of the drawbars has been modified in order to address the problems shown below. These new drawbars are available to order now.

Problems

- Failure to engage the drive motor fully at the drive spline.
- Poor thread engagement of the tool holder.

Design changes

- The drawbar is now hardened.
- The drawbar has been lengthened for more thread engagement.
- The drive splines have been lengthened for better engagement.

Part numbers

Order this	If you have this
22605	Two-axis K2 or K3; DPM E2; DPM SX2
22641-CAT or 22641-NMTB	Two-axis K4; Sport B5; DPM5; DPM SX3; DPM SX5; DPM S5
22603-CAT or 22603-NMTB	TRM; DPM/AGE3, Sport B3; DPM S3
21660-CAT or 21660-NMTB	DPMV3 with 2-piece head*; DPMV5 with 2-piece head*
23171- CAT or 23171-NMTB	DPMV3 with 1-piece head*; DPMV5 with 1-piece head*; FHM5
24165-CAT or 24165-NMTB	DPMV7; FHM7
24450-CAT or 24450-NMTB	Three-axis K4
24347	Three-axis K2 or K3

BT40 drawbars are available by special order only.

*You can tell from the letter code in the machine serial number if you have a 1 or 2-piece head.

- V3 with a 1-piece head – BJ
- V5 with a 1-piece head – BK
- V3 with a 2-piece head – AV
- V5 with a 2-piece head – AW

©2006 Southwestern Industries Incorporated. All rights reserved.

The information contained in this document represents the current view of Southwestern Industries, Inc., on the issues discussed as of the date of publication. Because Southwestern Industries must respond to changing market conditions, it should not be interpreted to be a commitment on the part of Southwestern Industries, and Southwestern Industries cannot guarantee the accuracy of any information presented after the date of publication.

This White Paper is for informational purposes only. SOUTHWESTERN INDUSTRIES MAKES NO WARRANTIES, EXPRESS OR IMPLIED, IN THIS DOCUMENT. WP090806